

MATERIAL SAFETY DATA SHEET

NPC

FOR COATINGS, RESINS AND RELATED MATERIALS

(Approved by U.S. Department of Labor "Essentially Similar" to Form OSHA-20)

DATE OF PREP.

5/13/75

R. 6/17/83

Section I

MANUFACTURER'S NAME U. S. Paint, Division of Grow Group, Inc.

STREET ADDRESS 831 S. 21st Street

CITY, STATE, AND ZIP CODE St. Louis, MO. 63103

EMERGENCY TELEPHONE NO.

INFORMATION TELEPHONE NO. (314) 621-0525

PRODUCT CLASS Solvent

MANUFACTURERS CODE IDENTIFICATION T0002
(T295)

DMS 2112 Type 1, Class 2

TRADE NAME Fast Evaporating Reducer and Equipment Cleaner

Section II - HAZARDOUS INGREDIENTS

INGREDIENT	Volume PERCENT	TLV		LEL	VAPOR PRESSURE in mm Hg 20°C
		PPM	mg/M ³		
Methyl Ethyl Ketone	100	200	590	1.8	71.2

Section III - PHYSICAL DATA

BOILING RANGE 172 to 178°F

VAPOR DENSITY ☒ HEAVIER. ☐ LIGHTER THAN AIREVAPORATION RATE ☐ FASTER ☒ SLOWER THAN ETHER

PERCENT VOLATILE BY VOLUME 100 WEIGHT PER GALLON 6.71

Section IV - FIRE AND EXPLOSION HAZARD DATA

Combustible Liquid 100°-200°F ☐

FLAMMABILITY CLASSIFICATION

Flammable Liquid 20°-100°F ☒

Non Flammable

EXTINGUISHING MEDIA


Dry Chemical or Foam ☐

FLASH POINT 28°F T.C.C.

LEL 1.8

UNUSUAL FIRE AND EXPLOSION HAZARDS Do not expose to spark or open flame

SPECIAL FIRE FIGHTING PROCEDURES



BOE-C6-0189926

Section V — HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE 200 PPM

EFFECTS OF OVEREXPOSURE Eye and upper respiratory irritant

ACUTE

CHRONIC

EMERGENCY AND FIRST AID PROCEDURES If exposed to excess vapor, remove to fresh air and seek medical attention. If splashed on skin wash thoroughly with soap and water. For eyes, flush immediately with plenty of water for 15 minutes and seek medical attention. If swallowed, CALL A PHYSICIAN IMMEDIATELY. Induce vomiting.

Section VI — REACTIVITY DATA

STABILITY ☐ UNSTABLE ☒ STABLE

INCOMPATIBILITY (Materials to avoid)

CONDITIONS TO AVOID Excess heat and/or oxidizing materials.

HAZARDOUS DECOMPOSITION PRODUCTS

HAZARDOUS POLYMERIZATION ☐ MAY OCCUR ☒ WILL NOT OCCUR

CONDITIONS TO AVOID

Section VII — SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED Affected area should be treated with an absorbing compound and then material placed in a tightly closed container.

WASTE DISPOSAL METHOD In accordance with local, state, and federal environmental control regulations.

Section VIII — SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION NIOSH/MSHA approved combination vapor/particulate or air supplied respirator.

VENTILATION Sufficient to keep air supply above threshold limit values.

PROTECTIVE GLOVES Rubber or Plastic

EYE PROTECTION Goggles

OTHER PROTECTIVE EQUIPMENT

Section IX — SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING Keep away from excess heat, sparks and flames.

DOL STORAGE CATEGORY

OTHER PRECAUTIONS